



To Whom it May Concern,

After removing the previous fabric repairs covering the cracks and the old cement/concrete from within the cracks in the tennis courts, we were able to assess the actual condition of the underlying asphalt more accurately. Some of the cracks were found to be very large in width (4"-5"). Two large pieces of asphalt that had broken off under the old fabric, came up with it during removal leaving potholes. With the size of the cracks and the potholes that needed to be patched, the conditions in several areas were beyond the limits of the Armor crack repair system and would almost certainly fail prematurely if installed. With the need for additional Armor crack repairs and asphalt patching, the cost increase to the project exceeds its value in comparison to repaving. The cost difference is less than \$10,000. For those reasons, Resurface recommends deleting the Armor Crack Repairs on the Tennis Courts and instead installing a 2" asphalt overlay of the courts. We feel that this is the best value option. Please contact us with any questions you may have.

Sincerely,

**Jeff Zingo**  
**Resurface Inc.**  
**Sport Court Estimator/Project Manager**