








LOUISE ARCHER ELEMENTARY SCHOOL			11.23.21	
EXTERIOR MATERIALS				
Keyed Designation	Material	Comments		
BR1	Face Brick 1	Red-brown to match existing	Lawerenceville Wirecut Flashed	
BR2	Face Brick 2	Brown	Continental 418	
BR3	Face Brick 3	Tan	Glen Gery Chesterfield	
BR4	Face Brick 4	Light Tan-Cream	Glen Gery Golden Dawn Wirecut	
CCS1 CSS	Cast Stone Cap Cast Stone Sill		Nelson Precast 144 Neutral Buff	
GFMU1	Ground Face Masonry Unit		Trenwyth Trendstone Plus Chocolate	
GFMU2	Ground Face Masonry Unit		Trenwyth Trendstone Plus Natural	

GFMU3	Ground Face Masonry Unit		Trenwyth Trendstone Plus Parchment	
	Mortar		Workrite WR 446 Mushroom	
MR1	Metal Roof		Cardinal Red	
MF1	Metal Fascia			
MP1	Flush Seam Metal Panel			
MF2	Metal Fascia		White	
MG2	Metal Gutter			
MC3	Metal Coping		Sierra Tan	
MF3	Metal Fascia			
MG3	Metal Gutter			
MP3	Flush Seam Metal Panel			
FCT2	Fiber Cement Trim		Paint P-20: White	
HPC-1	High-performance coating for exposed steel		Sierra Tan	
LAWP	Laminated Aluminum Panel		Citadel Envelope 2000 Bone White	

ACW	Aluminum Curtain Wall		Sierra Tan	
ASF	Aluminum Storefront			
AW	Aluminum Window		White	