

Standing-seam metal roof panels (ATAS-16 Rocky Grey)






Photo #1 – Exterior view of Bowman House roof



Photo #2 – View of Truss T2 showing several cut web members





Photo #6 – Typical existing roof construction – rafters only, all web members removed



Photo #7 – ~~Cut diagonal at dormer location~~




Photo #8 – Uncovered roof opening at exhaust fan