

T-Mobile Site 7WAC050A

Existing Conditions




TMBXX-6516-A2M antenna
being replaced

Alpha Sector
Remove (1) Andrew TMBXX-6516-A2M
antenna and replace with (1) Ericsson
AIR6449 B41 antenna.



TMBXX-6516-A2M antenna
being replaced

Beta Sector
Remove (1) Andrew TMBXX-6516-A2M
antenna and replace with (1) Ericsson
AIR6449 B41 antenna.



AIR6449 B41 antenna to be installed

Gamma Sector
Install (1) Ericsson AIR6449 B41
antenna.





AIR6449 B41 antenna to be installed

Delta Sector
Install (1) Ericsson AIR6449 B41 antenna.